

Oil Field Environmental Incident Summary

Incident: 20140130164746 **Date/Time of Notice:** 01/30/2014 16:14

Responsible Party: AD Custom Trucking

Well Operator: KODIAK OIL & GAS (USA) INC.

Well Name: CHARGING EAGLE 16-21-16-1HA

Field Name: TWIN BUTTES

Well File #: 23953

Date Incident: 1/30/2014

Time Incident:

Facility ID Number:

County: DUNN

Twp: 147

Rng: 92

Sec: 21

Qtr:

Location Description:

Submitted By: Jared Astle

Received By:

Contact Person: Jared Aslte
2540 4th St. West #208
Dickinson, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Blowout

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units
Oil	0	barrels	0	barrels
Brine	4	barrels	4	barrels
Other	0	barrels	0	barrels

Followup **Units**

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

I don't feel that there is any potential impacts at this time.

Action Taken or Planned:

Another truck that was near by came over and sucked up any water that was standing on the surface of the frozen ground. A clean up crew/company was called in and they scraped up any soil and materials that were contaminated on the location as a result of the spill.

Wastes Disposal Location: Chimney Butte Landfill

Agencies Involved: Environmental Resources, and TERO dept.

Updates

Date: 1/30/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, possibly from a truck hose blowout, remained on location within the diking, according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental and BIA.